03500.017851 PATENT

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
	:	Examiner: L. Martin
KOICHIRO NAKAZAWA, ET AL.	)	
	:	Group Art Unit: 2853
Appl. No.: 10/765,037	)	
	:	Confirmation No.: 9610
Filed: January 28, 2004	)	
	:	
For: INK-JET RECORDING APPARATUS	)	
D	:	
Patent No.: US 7,226,157 B2	)	
	:	1 22 2000
Issued: June 5, 2007	)	January 23, 2009

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Scott D. Malpede/

Scott D. Malpede Attorney for Patentees Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

MAW:eyw

Form #33 - 2 -

# UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

**PATENT NO.** : US 7,226,157 B2

**DATED** : June 5, 2007

INVENTOR(S): NAKAZAWA, ET AL. Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 2:

Line 22, "show through" should read --show-through--.

Line 38, "show through" should read --show-through--.

Line 67, "show through" should read --show-through--.

## COLUMN 3:

Line 3, "show" should read --show- --.

Line 19, "show through" should read --show-through--.

#### COLUMN 10:

Line 55, "show through" should read --show-through--.

## COLUMN 11:

Line 47, "show through" should read --show-through--.

## COLUMN 12:

Line 52, "show through" should read --show-through--.

# COLUMN 13:

Line 7, "show through" should read --show-through--.

Line 48, "show through" should read --show-through--.

#### COLUMN 20:

Line 44, "splash" should read --splash,--.

#### **MAILING ADDRESS OF SENDER:**

PATENT NO. <u>US 7,226,157 B2</u>

No. of add'l. copies @ 30¢ per page

30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

FITZPATRICK, CELLA, HARPER & SCINTO

# Staple Here Only! SINI WILL S. HERE

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

**PATENT NO.** : US 7,226,157 B2

**DATED** : June 5, 2007

INVENTOR(S) : NAKAZAWA, ET AL.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 23:

Line 59, "show" should read --show- --.

#### COLUMN 24:

Line 37, "Show Through:" should read --Show-Through:--.

Line 42, "show through." should read --show-through.--.

#### COLUMN 25:

Table 1, "Show through" (in column 9) should read -- Show-through--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,226,157 B2</u>

No. of add'l. copies @ 30¢ per page

Page 2 of 2

